

srs-2 manual pdf

AI generated article from Bing

Driver restraint code 930958 - BimmerFest BMW Forum

Hi all. I recently acquired a 2013 535i that needs a little tlc. One of the issues is the driver restraint system code 930958 as read by bluedriver. It is described in that app as "ZK15: active headrest driver :resistance to big". So far I have replaced the battery, checked the plugs and wiring...

Internal failure of the SRS Unit and inspection.

Option 2: Fix the problem. I have searched over the holiday but I am not find specifics on the problem beyond they SRS flash code listing that states that al 5-X,6-X,7-X, and 8-X are "Internal failure of the SRS Unit". The SRS unit flash code list does not link to troubleshooting procedures like other flashcode directories.

Troubleshooting SRS error code 112 "seat occupancy...

Did you reset the SRS code after installing the dongle? Ed in San Jose '97 540i 6 speed aspensilber over aubergine leather. Build date 3/97. Golden Gate Chapter BMW CCA Nr 62319.

Airbag Module Reset | BMW Forum - BimmerFest BMW Forums

I would just buy an airbag module on ebay before resetting, but notice the reset sites say: Scanners read "crash data stored". Would Creator C310 display that? I do know my car was in an accident from the previous owner and the SRS light was on when I bought it. Doesn't say crash data...

DIY SRS airbag light reset (E39) - BimmerFest BMW Forum

EXCEPT I can't find anyone who knows how to reset the SRS airbag light (using the pin cluster under the hood/bonnet) without buying a reset tool or going to the dealer.

Srs error | Honda Insight Forum

The SRS and other sub system codes don't show with the fuse box short. When I traced out that OBDII plug short mentioned , one pin to ground , one pin to EPS power steering ?

Resetting the SRS code on dash - Honda Insight Forum

The SRS indicator light comes on for about six second and goes off. Remove the SCS service connector from the MES connector within 4 seconds after the SRS indicator light went off.

B800 SRS Scan and Reset Tool - BimmerFest BMW Forum

No. SRS = Supplemental Restraint System, aka air bags. It's the best low-cost BMW scan tool specifically for this task. Get a general-purpose scan tool for reading P-codes. You'll need a BMW-specific tool to read all other codes besides engine and transmission. Good tools like this are in the \$5-10k range.

SRS Light Code - Seatbelt Buckle Switch? - BimmerFest BMW Forum

The passenger side connector is also a common failure -- the SRS light stays on for a couple minutes as the system tries to figure out through the seat belt receptacle whether the shotgun seat is occupied. When the results are inconclusive, the passenger airbag arms and the light goes out. My 540i has been doing this for 15 years.

Z3 SRS light and fault codes - BimmerFest BMW Forum

Hi guys, got my SRS light on so I ordered the Peake R5/SRS Scan from LeatherZ and got the following fault codes: 16 Sensor, side airbag, right, parameter fault 17 Sensor, side airbag, right, data fault. Is this something I can take care off myself? or is a visit to the dealer necessary? TIA...